

Contents: **Release Notes**
 Client: **EbV**

Table of contents:

1	Update 2.2.38891, Relay V2.2. Rev. 13 from 22.07.2021	-----1
2	Troubleshooting	-----1
2.1	heatcon! EC, heatapp! base, heatapp! base T2B	-----1
2.2	heatapp! gateway	-----1
3	Safety instructions	-----2
4	Update path for manual call	-----2

1 Update 2.2.38891, Relay V2.2. Rev. 13 from 22.07.2021

Update available for

heatapp! base	heatapp! base T2B	heatapp! gateway
heatcon! EC 1351	heatcon! EC 1321	heatapp! head office

ATTENTION: On devices prior to version 2.2.xxx, this update must be installed before **01.08.2021**, **otherwise** the **update capability will be lost** and installation via the Internet will no longer be possible.

2 Troubleshooting

2.1 heatcon! EC, heatapp! base, heatapp! base T2B

- The function "external request or modem function on room, heating circuit and hot water via potential-free request contact" can now be activated.
- Adjustment of the 0-10 V interface.

2.2 heatapp! gateway

- Troubleshooting

3 Safety instructions

It is always advisable to make a data backup **before** updating. To do this, select "Settings > System > System management" in the app and create a data backup on a USB memory stick that is plugged into the heatcon! EC.

Hint: A data backup can only be made for heatapp! base / base T2B / heatcon! EC. A data backup of the heatapp! gateway is not possible.

After the data backup, carry out the updates. Do **not disconnect the power supply of the units during the update**. Depending on the size of the system and the speed of the Internet connection, the updates can take up to 20 minutes and are only completed when the LED(s) light up dark green again.

4 Update path for manual call

Settings > System > System Management

Settings > Gateway > System Management

We wish you a lot of fun with your system.

Your EbV - Team

For questions, please contact our technical support team

E-mail: Support@ebv-gmbh.de

Phone: 02736 44 305 900