

Contents: **Release Notes**  
Client: **EbV**

## 1 Update 2.2.40971, Relay V2.2 Rev. 41 from 02.02.2024

Update available for :

heatapp ! base	heatapp ! base T2B	heatapp ! gateway
heatcon! EC 1351	heatcon! EC 1321	heatapp ! Zentrale

## 2 Update content

- Bugfixing Wintersperre (only heatcon! EC)
- Bugfixing Kaskade via RS485 (only heatcon! EC)  
Qualification of further window contacts (list of heatapp ! checked components can be found [here](#))

## 3 Safety instructions

It is always advisable to make a data backup **before** updating. To do this, select "Settings > System > System management" in the app and create a data backup on a USB memory stick that is plugged into heatcon! EC/heatapp! base/heatapp! base T2B

**Note:** A data backup of the heatapp! gateway is not possible.

After the data backup, carry out the updates. Do **not disconnect the power supply of the units during the update**. Depending on the size of the system and the speed of the Internet connection, the updates can take up to 20 minutes and are only completed when the LED(s) light up dark green again.

## 4 Update path for manual call

Settings > System > System Management

We wish you a lot of fun with your system.

## Your EbV - Team

For questions please contact our technical support

e-mail: [Support@ebv-gmbh.de](mailto:Support@ebv-gmbh.de)

Phone: 02736 44 305 900